

170309 N.

December 8, 1998

Vince L. Epps IDEM 100 North Senate Avenue P.O. Box 6015 Indianapolis, IN 46206-6015 Michael McAteer USEPA, HSRW-6J 77 West Jackson Blvd. Chicago, IL 60604-3590

Re: Enviro-Chem RRA, Zionville, Indiana,

Results of Pumping Test Performed on Hot Spot #2 Well (Well HS-2)

Dear Sirs:

Recently Versar, Inc. (Versar) conducted a 120 hour pumping test on Hot Spot Well HS-2 located within the southern portion of the subject site, and conducted laboratory analyses on samples of the containerized pumping water. The work was performed in accordance with the October 7, 1998 Revised Hot Spot #2 Work Plan prepared by Versar on behalf of the Enviro-Chem Trust and submitted to Indiana Department of Environmental Management (IDEM) and the U.S. Environmental Protection Agency (USEPA). The purpose of the pumping test was to evaluate the possibility (if any) of a hydraulic connection between the two Hot Spot areas and/or the surrounding wells, and to assess the quality of the groundwater beneath the Hot Spot #2 area. The site plan/well location map is included as Figure 1.

Procedures

The Well HS-2 pumping test began on November 9, 1998, and lasted approximately 120 hours, ending on November 14, 1998. During the test, groundwater elevations were monitored within the pumping well (Well HS-2), the two Hot Spot #1 wells (Wells HS-1 and HS-1A), and surrounding on-site monitoring wells, specifically Wells S-2, S-3, T-9 and IW-5. Drill logs, including well construction diagrams, for the three hot spot wells (Wells HS-1, HS-1A, and HS-2) are included in Attachment A. The other wells were not installed by Versar.

Prior to the beginning of the pumping test, pressure transducers for a two channel In-Situ Hermit[™] Data Logger were installed near the bottom of Wells HS-1 and HS-2 in order to collect water level measurement. Periodic manual water-level measurements were collected from all seven wells, including HS-1 and HS-2. The water level readings are included in Attachment B. Groundwater drawdown versus time plots of the water level readings are enclosed as Attachment C. Permeability calculations, including a semi-log plot of drawdown versus time for the pumping well (Well HS-2), are presented in Attachment D.



Based on yield values obtained during development of the recently installed Well HS-2, the pumping rate for the test was set at 2.5 gallons per minute (gpm). The intake of the pump, a Grundfos™ ReadyFlow2, was placed approximately one foot from the bottom of the 16 foot deep recovery well. An in-line flow meter was used to gauge the 2.5 gpm flow rate. The purge water was discharged into a clean Frac tank present at the site. Two samples of the stored purge water were collected within the first and last 24 hours of the test. The samples were collected from a manhole in the top of the Frac tank via disposable bailers, and were placed in laboratory-supplied containers. The two purge water samples, labeled FT and FT2, respectively, were placed on ice and delivered by courier to National Environmental Testing, Inc. (NET) of Indianapolis, Indiana for volatile organic compounds (VOCs) analysis using USEPA Method 8260. The laboratory analytical results are enclosed as Attachment E.

Results and Conclusions

Versar has the following results and conclusions based upon the compilation and assessment of the field observations and laboratory analytical results derived from the recent pumping test of Well HS-2 located within Hot Spot #2:

• A hydraulic connection was observed between the pumping well (Well HS-2) in Hot Spot #2 and the deeper of the two Hot Spot #1 wells (Well HS-1A).

As indicated in the drawdown versus time plots for Wells HS-2 and HS-1A, the cone of groundwater depression associated with the pumping in Well HS-2 had a maximum sustained drawdown of approximately 1.0 foot in Well HS-2 and of approximately 0.6 foot in nearby Well HS-1A. Furthermore, the drawdown curves for both wells are similar in shape and response time.

• None of the remaining wells monitored during the pumping test, including Hot Spot #1 well (HS-1), were effected by the drawdown in Well HS-2, but all of the wells were affected by a local rain storm event.

The drawdown curves for Wells HS-1, S-2, S-3, T-9 and IW-5 appeared unaffected by the pumping in Well HS-2. The only regional hydraulic impact to these wells was the groundwater recharge associated with two consecutive periods of heavy rain within one storm event, which commenced shortly after the initiation of the test and lasted approximately 16 hours. The effect that this storm had on the regional groundwater can be observed in all seven wells as a single or double "hump" in the well drawdown curves between approximately 0 minutes and 2,500 minutes (see Attachment C).



• Well HS-2 (Hot Spot #2 Well) yielded a flow of 2.5 gpm and an average hydraulic conductivity of 1.17x10⁻⁵ ft/sec in the saturated zone located at a depth of 13 to 16 feet within the well.

The hydraulic conductivity for Well HS-2 was calculated from the log-log plot of hydraulic head versus time curve for the first 20 minutes of the pumping test (see Attachment E), prior to the onset of the rain storm event. The calculated hydraulic conductivity and observed yield for Well HS-2 are consistent with data collected during the installation of this well. Specifically, at a depth of 12 to 14 feet the well intersects a sand and gravel layer. The 1.17x10⁻⁵ ft/sec hydraulic conductivity is typical of sandy units (Freeze and Cherry, 1979), such as the one observed in the lower portion of Well HS-2.

• The samples collected from the purge water stored in the on-site Frac tank had elevated VOC concentrations in excess of the Acceptable Subsurface Water Concentrations included in *Revised Exhibit A* Table 3-1 Cleanup Standards.

Concentrations of several VOCs including 1,1-dichloroethene, cis-1,2-dichloroethene, methylene chloride, trans-1,2-dichloroethene, tetrachloroethene, 1,1,1-trichloroethane, and vinyl chloride exceeded the Acceptable Subsurface Water Concentrations included in *Revised Exhibit A* Table 3-1 Cleanup Standards.

Recommendations

Based on the results of the pumping test and groundwater laboratory analyses, Versar has the following recommendations which are consistent with the October 7, 1998 Revised Hot Spot #2 Work Plan:

- Both hot spot areas and the Frac tank purge water will be treated with Fenton reagents. However, since a hydraulic connection exists between Wells HS-2 and HS-1, the Hot Spot #2 area will be treated three to six weeks prior to the Hot Spot #1 area. The water in the Frac tank will be treated at the same time as the Hot Spot #2 area, and will subsequently be pumped through the on-site water treatment system for polishing before being discharged.
- The effectiveness of the Fenton reagent treatment will be monitored via by-weekly sampling (for a period of two months) of Wells HS-2, HS-1 and HS-1A for VOCs, semi-volatile organic compounds (SVOCs), total organic carbon (TOC), dissolved oxygen (DO), redox potential, hydroxyl radical, pH, temperature, and conductivity.





• If residual organics remain in the wells of concern, a second Fenton reagent application will be considered upon an analysis of the data. The treatment effectiveness will be measured with respect to water samples taken from the hot spot and recovery wells that are assumed to be in equilibrium with soil compared to the Acceptable Subsurface Water Concentrations included in *Revised Exhibit A* Table 3-1 Cleanup Standards.

If you have any questions or comments please contact George at (215) 788-7844, extension 222.

Very truly yours,

David V. Stockar, P.E. Senjor Hydrogeologist

FOR

G. J. Anastos, Ph.D., P.E.

Project Manager

Attachments

cc:


R Ball

N Bernstein M Dowiak

R Hutchens

References

Freeze, R. Allen & John A. Cherry (1979), Groundwater, Prentice-Hall, Inc., Englewood Cliffs, N.J.





ATTACHMENTS



ATTACHMENT A Drilling Logs

Date Drilled : 10/19/98 Casing Length : 6' Casing Type Log By : DVS : PVC **Drilling Company** : Earth Exploration int. Water Level : 9 (bgs) Driller : Scott 4-Hr. Water Level : 12.38 (bgs) Sampling Method : Split Spoon **Drilling Method** : Auger Log of Well HS-2 - Hot Spot #2 Screen Diameter : 4" Slot Size : .20 **Enviro-Chem Site** Zionsville, Indiana Screen Length : 10' Casing Diameter : 4" Well1: HS-2 Count SRAPHIC Elev.: Depth PID **USCS** DESCRIPTION Blow (READINGS FEET (PPM) 0 FILL: SAND, crushed stone (limestone), sand ,silt 5 4 FL 1 Cement Grout 3 4 2 CLAY FILL: Dense clay, organic-rich, brown, no odor no 2 Casing staining 3 CL-FL 3 0 3 Bentonite Seal 4 4 CLAY FILL: Silty, some sand grains, organic plant material, slight odor 2 4 5 CL-FL 62 3 5 6 CLAY FILL: Silty, some fine sand, organic-rich, some discolorization, slight odor 2 2 CL-FL 37 7 3 2 8 CLAY: Silt, quartz sand, organic plant material, gray-brown, slight odor, stratified and dense 1 1 CL 81 9 2 2 10 2 CLAY: Dense, gray homogenous, wet, slight staining CL 4 11 54 Screen 10 SAND: Fine to coarse, coarsening downward, typical SM Sand Pack stream channel sequence, slight odor, slight staining 8 12 GRAVEL: pebbles to cobbles, rounded, quartz-rich, 3 water bearing zone, black staining, slight odor 7 GC 52 13 7 8 14 CLAY: Silty, compressed zone with interbedded pebbles, 6 top of sand lense, medium to coarse, slight odor 17 CL 121 15 32 13 16 SAND: Silty at top, medium to fine grained at bottom, quartz-rich, densely compacted glacial till, slight odor, no 27 35 SM 17 staining 32 38 18 SILT: Densley compacted silty glacial till with sand and C:\tiw\3709\hs-3.bor 27 pebbles intermixed, no odor 33 19 MH 2 Bentonite Seal 51 49 20 LOG OF BORING HS-2 - HOT SPOT #2

PROJECT: ENVIRO-CHEM OWNER: N		NA	SKETCH MAP:	
LOCATION: ZIONSV	CATION: ZIONSVILLE, IN W.O. #:		2495-1010	ND - NOT DETECTED
BORING #: HS-1A TOTAL DEPTH: 28'		TH: 28'	DIAMETER: 8"	VPPM - VAPOR PARTS PER
SURFACE ELEV: NA	URFACE ELEV: NA WATER LEVEL: NA		24-HRS: NA	MILLION
SCREEN DIA: 4"	LENGTH: 1	0,	SLOT SIZE: 0.020	SS - SPLIT SPOON
CASING DIA: 4"	LENGTH: 1	7'	TYPE: PVC	F - FINE M - MEDIUM
DRILLING CO: TOP FLIGHT DRILLING ME			ETHOD: HSA	C – COARSE
DRILLER: NICK	LOG BY: VE	B DATE	DRILLED: 03/16/98	NOTES:

SS-43 8-11 6 10'-10.2' BROWN M-C SAND, SATURATED 12-12									
2 TRACE SILT, TRACE F-C SAND, WET							COUNT/ RQD/		(COLOR, TEXTURE, STRUCTURES,
TRACE SILT, TRACE F-C SAND, WET Solution State State	1	ジスツ	7		, `\				0'-7' GREY BROWN CLAY, LITTLE TO
10 10 10 10 10 10 10 10	2	$\langle \langle \langle \langle \rangle \rangle \rangle$		M					TRACE SILT, TRACE F-C SAND, WET
5 SAND, TRACE M-C GRAVEL, DAMP, NO OD	3	ななべ	7		∇			50	DISTURBED, SLIGHT ODOR
SS-43 8-11 6 10'-10.2' BROWN M-C SAND, SATURATED 12-12	4		∇		7				7'-10' GREY CLAY, SOME SILT, TRACE F
12-12	5	KKK	7 5	ľ					SAND, TRACE M-C GRAVEL, DAMP, NO ODOR
SS-44 10-11 10.2'-11.8' GREY CLAY, SOME SILT, TRACE	6				$ \cdot $	SS-43	8-11	6	10'-10.2' BROWN M-C SAND, SATURATED,
9	7	$\lambda \lambda \lambda \langle \lambda \rangle$	∇		7		12-12		NO ODOR
10	8		2 4		\triangle	SS-44	10-11		10.2'-11.8' GREY CLAY, SOME SILT, TRACE
10	9	· ·	∇		, `		14-16		F-C SAND, DAMP, NO ODOR
11	10	÷.—.	$\lfloor ullet \rfloor$	<u> </u>	$'$ \Box	SS-45	6-7	41	11.8'-12.4' BROWN M SAND, SATURATED,
13	11		7		\vee		8-14		
14	12		∇		7	SS-46	11-12	11	12.4'-13.8' GREY CLAY, SOME SILT, TRACE
15	13	Bessel :	7		abla		12-15		F SAND, DAMP, NO ODOR
15 12-14 SLIGHT ODOR 16 253555557	14				,	SS-47	6-8	34	13.8'-14.4' BROWN M SAND, SATURATED,
17	15	· · · ·	$ \vee $		/		12-14		SLIGHT ODOR
18	16	2222	7		∇	SS-48	5-4	15	14.4'-15.2' GREY & BROWN CLAY AND
19 12-18 15.6'-17.8' GREY CLAY & SILT, TRACE 20 SS-50 9-10 3.5 F-C SAND/GRAVEL, DAMP, NO ODOR	17	<u>~</u>					12-12		SILT, TRACE F-C SAND/GRAVEL, DAMP
19	18	<u> </u>		<u> </u>		SS-49	10-11	15.7	15.2'-15.6' BROWN M SAND, SATURATED,
	19			<u> — </u>			12-18		
21	20					SS-50	9-10	3.5	
22 SS-51 3-4 13 23 7-12 21'-25' GREY CLAY, LITTLE SILT, DAMP,	21						10-11		17.8'-21' BROWN POORLY SORTED SAND,
23 7-12 21'-25' GREY CLAY, LITTLE SILT, DAMP,	22	<u> </u>				SS-51	3-4	13	
24 — — — SC 50 7 6 7 SLIGHT ODOR	23		• • • • • • • • •	;			7-12		21'-25' GREY CLAY, LITTLE SILT, DAMP,
	24					SS-52	3-6	3	SLIGHT ODOR
25	25			<u> </u> — 🖁			10-10		

DRILL LOG HS-1A

PROJECT: ENVIRO-	CHEM OWNER	: NA	SKETCH MAP:
LOCATION: ZIONSVI	LLE, IN W.O. #	: 2 495 –1010	ND - NOT DETECTED
BORING #: HS-1A TOTAL DEPTH: 28'		DIAMETER: 8"	VPPM - VAPOR PARTS PER
SURFACE ELEV: NA	WATER LEVEL: NA	24-HRS: NA	MILLION
SCREEN DIA: 4"	LENGTH: 10'	SLOT SIZE: 0.020	SS - SPLIT SPOON
CASING DIA: 4"	LENGTH: 17'	TYPE: PVC	F - FINE M - MEDIUM
DRILLING CO: TOP	FLIGHT DRILLING	METHOD: HSA	C - COARSE
DRILLER: NICK	LOG BY: VFB DA	TE DRILLED: 03/16/98	NOTES:

		WELL	SAMPLE #	BLOW COUNT/ RQD/ %REC.	PID READING	DESCRIPTION/SOIL CLASSIFICATION (COLOR, TEXTURE, STRUCTURES, MOISTURE)
26		 =	SS-53	6-13	1	25'-25.3' BROWN SAND, SATURATED,
27		<u> </u>		15-21		NO ODOR
28	000000000000					25.3'-27' GREY CLAY, LITTLE SILT, NO
29	 ·					ODOR, DAMP
30						27'-27.3' BROWN SAND, SATURATED, NO
		i I				ODOR
						27.3'-28' GREY CLAY, LITTLE SILT, DAMP,
						NO ODOR
			ļ			
			<u> </u>			
		<u> </u>				
					·	
			! !			
		<u> </u>				
		li .				
					-	
Li	· 	<u></u>	 <u> </u>	<u> </u>		

PROJECT: ENVIRO-CHEM OWNER: N			NA	SKETCH MAP:
LOCATION: ZIONSVI	LLE, IN	W.O. #:	2495 -1010	ND - NOT DETECTED
BORING #: HS-1	TOTAL DEPT	PTH: 22' DIAMETER: 8"		VPPM - VAPOR PARTS PER
SURFACE ELEV: NA	WATER LEVE	VEL: NA 24-HRS: NA		MILLION
SCREEN DIA: 4"	LENGTH: 5'		SLOT SIZE: 0.020	SS - SPLIT SPOON
CASING DIA: 4"	LENGTH: 11	•	TYPE: PVC	F - FINE M - MEDIUM
DRILLING CO: TOP	G CO: TOP FLIGHT DRILLING METHOD: HSA			C - COARSE
DRILLER: NICK	LOG BY: VF	B DATE	DRILLED: 03/12/98	NOTES:

							
DEPTH	GRAPHIC	WE	ELL	SAMPLE	BLOW	PID	DESCRIPTION/SOIL CLASSIFICATION
(FEET)	LOG	CONST	RUCTION	#	COUNT/	READING	(COLOR, TEXTURE, STRUCTURES,
					RQD/		MOISTURE)
					%REC.		
1	アイバン	⊘ ·	2. 4				
2	1	·					0'-6' GREY AND BROWN CLAY, LITTLE
3	$\langle \lambda \lambda \lambda \rangle$	<u>· · ·</u>	[`.]			80	SILT, TRACE F-C SAND, WET, DISTURBED
4	小火火	Y ·]	γΥ	_			PESTICIDE ODOR
5	7. V.V.	. 7					
6	/	47.	F 4	SS-18	815	54	6'-9.8' GREY CLAY, SOME SILT, TRACE
7	<u>→</u>	·			17-32		F-M SAND, TRACE F-M GRAVEL (WELL
8	- <u>`</u>			SS-19	9-10	12.5	ROUNDED), DAMP, MOTTLED, SLIGHT ODOR
9	<u>6 8</u>	$\nabla \cdot$	þ4		13-22		SORTED, SATURATED, NO ODOR
10	<i>_</i>			SS-20	5-5	20.4	9.8'-10' BROWN F-M GRAVEL, SATURATED,
11	<u> </u>				17-12		SLIGHT ODOR (CHLORINATED SOLVENT)
12	<u>-</u>			SS-21	3-5	3.0	10'-12' GREY CLAY, SOME SILT, MOIST,
13	<u> </u>	<u> </u>			8-9		NO ODOR
14	<u> </u>	- 	— ————————————————————————————————————	SS-22	6-8	114.7	12'-12.2' BROWN F-M SAND & GRAVEL,
15	0.000	-			11-12		SATURATED, ODOR (CHLORINATED SOLVENT)
16	= =	-		SS-23	3-4	ND	12.2'-14' GREY CLAY, LITTLE SILT, DAMP,
17					7-10		NO ODOR
18				SS-24	4-5	ND	14'-14.8' BROWN C SAND, STRONG ODOR
19		$\vec{\nabla} \cdot \vec{\nabla}$	2, 42, 4		7-9		(CHLORINATED SOLVENTS)
20		·		SS-25	4-6	ND	14.8'-19.5' GREY CLAY, LITTLE SILT,
21		. V :	\ \ .\.\.		9-9		DAMP, NO ODOR
22		∇ . ∇	7. 🗸 . 🕏				19.5'-19.6' BROWN F SAND, SATURATED,
23		ı					NO ODOR
24							19.6'-22' GREY CLAY, TRACE SILT, DAMP,
25			ľ				NO ODOR
26							



ATTACHMENT B Water Level Field Data

HS-2 Pumping Test
Test Site: Enviro-Chem
Location: Zionsville, Indiana
Depth-to-water: 12.410'

Well HS-2 Readings
Test Conducted on: 11-09-98
Test Conducted by: TK & TJW

Reading	Pump test duration	Water level	Change in Water Level	Comments:
	[min.]	[ft]	[ft]	
Pre-test	0.0000	12.410	0.000	
1	0.0000	12.856	-0.446	
2	0.0166	12.847	-0.437	
3	0.0333	12.850	-0.440	
4	0.0500	12.850	-0.440	
5	0.0666	12.850	-0.440	
6	0.0833	12.847	-0.437	
7	0.1666	12.875	-0.465	
8	0.2500	12.894	-0.484	
9	0.3333	12.894	-0.484	
10	0.4166	12.913	-0.503	
11	0.5000	12.961	-0.551	. 4
12	0.5833	13.065	-0.655	
13	0.6666	13.056	-0.646	
14	0.7500	13.037	-0.627	
15	0.8333	13.037	-0.627	
16	0.9166	13.037	-0.627	
17	1	13.103	-0.693	
18	2	13.503	-1.093	
19	3	13.683	-1.273	
20	4	13.759	-1.349	
21	5	13.826	-1.416	
22	6	13.883	-1.473	
23	† Š	13.930	-1.520	
24	8	13.959	-1.549	
25	9	13.987	-1.577	
26	10	14.006	-1.596	
27	20	14.120	-1.710	
28	30	13.189	-0.779	··· · · · · · · · · · · · · · · · · ·
29	40	13.360	-0.950	
30	50	12.980	-0.570	
31	60	12.210	0.200	
32	70	12.961	-0.551	
33	80	12.676	-0.266	
34	90	12.619	-0.209	
35	100	12.609	-0.199	
36	200	13.122	-0.712	
37	300	13.141	-0.731	
38	400	13.141	-0.731	
39	500	13.113	-0.703	
40	600	13.084	-0.674	
41	700	13.046	-0.636	
42	800	13.037	-0.627	·
43	900	13.037	-0.627	
44	1,000	12.305	0.105	
45	1,200	12.153	0.257	
46	1,400	12.371	0.039	
47	1,600	12.486	-0.076	
48	1,800	12.562	-0.152	
49	2,000	12.600	-0.190	 '2
50	2,200	12.657	-0.247	

HS-2 Pumping Test Well HS-2 Readings Test Site: Enviro-Chem Test Conducted on: 11-09-98 Location: Zionsville, Indiana Test Conducted by: TK & TJW Depth-to-water: 12.410' Change in Water Level Reading Pump test duration Water level Comments: [min.] [ft] [ft] -0.275 51 2,400 12.685 2,600 52 12.723 -0.31353 2,800 13.170 -0.7603,000 13.208 -0.798 54 13.236 -0.826 55 3,200 56 3,400 13.265 -0.85557 3,600 -0.883 13.293 13.322 58 3,800 -0.912 59 4.000 13.331 -0.92160 4,200 13.331 -0.921 4,400 13.341 61 -0.931 62 4,600 13.360 -0.950 63 4,800 13.379 -0.969 64 5,000 13.396 -0.988 -0.998 65 5,200 13.408 5,400 13.396 -0.988 66 67 5,600 13.274 -0.86468 5,800 13.274 -0.864 69 13.303 -0.893 6,000 70 6,200 13.322 -0.912 6,400 13.322 -0.912 <u>71</u> 72 6,600 13,331 -0.921 73 6,800 13.350 -0.940 74 7,000 13.332 -0.922 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

HS-2 Pumping 7	est	Well HS-1 Readings			
Test Site: Envir		Test Conducted on: 11-09-98			
Location: Zions			Test Conducted by: TK & TJW		
Depth-to-water:	7.245'				
Reading	Pump test duration	Water level	Change in Water Level	Comments:	
1	[min.]	[ft]	[ft]		
1	0.0000	7.245	0.000		
2	0.0166	7.235	0.010		
3	0.0333	7.245	0.000		
4	0.0500	7.235	0.010		
5	0.0666	7.235	0.010	· · · · · · · · · · · · · · · · · · ·	
6	0.0833	7.235	0.010		
7	0.1666	7.235	0.010		
8	0.2500	7.245	0.000		
9	0.3333	7.235	0.010		
10	0.4166	7.245	0.000		
11	0.5000	7.245	0.000		
12	0.5833	7.245	0.000		
13	0.6666	7.245	0.000		
14	0.7500	7.245	0.000		
15	0.8333	7.245	0.000		
16	0.9166	7.245	0.000		
17	11	7.245	0.000		
18	2	7.245	0.000		
19	3	7.245	0.000		
20	4	7.245	0.000		
21	5	7.245	0.000		
22	6	7.245	0.000		
23	7	7.245	0.000		
24	8	7.245	0.000		
25	9	7.245	0.000		
26	10	7.245	0.000		
27	20	7.245	0.000		
28	30	7.245	0.000		
29	40	7.245	0.000		
30	50	7.245	0.000	<u> </u>	
31	60	7.245	0.000		
32	70	7.245	0.000		
33	80	7.245	0.000	<u> </u>	
34	90	7.245	0.000		
35	100	7.245	0.000		
36	200	7.228	0.019		
37	300	7.207	0.038		
38	400	7.170	0.075		
39	500	7.086	0.159		
40	600	6.889	0.356		
41	700	6.693	0.552		
42	800	6.533	0.712		
43	900	6.543	0.702		
44	1,000	6,939	0.308		
45	1,200	0,606	0.347		
46	1,400	6.833	0.412		
47	1,600	0.647	0.598		
48	1,800	6.824	0.421		
49	2,000	6.936	0.309		
50	2,200	7.001	0.244		

HS-2 Pumping Test Well HS-1 Readings Test Site: Enviro-Chem Test Conducted on: 11-09-98 Location: Zionsville, Indiana Test Conducted by: TK & TJW Depth-to-water: 7.245' Reading Pump test duration Water level Change in Water Level Comments: [min.] [ft] [ft] 2,400 7.048 0.197 51 2,600 7.086 0.159 52 53 2,800 7.104 0.141 54 3,000 7.142 0.103 55 3,200 7.151 0.094 7.170 56 3,400 0.075 3,600 7.188 0.057 57 58 3,800 7.217 0.028 59 4,000 7.235 0.010 60 4,200 7.226 0.019 7.226 4,400 61 0.019 7.245 0.000 62 4,600 63 4,800 7.245 0.000 64 5,000 7.245 0.000 5,200 -0.009 65 7.254 66 5,400 7.254 -0.009 5,600 7.245 0.000 67 7.245 0.000 68 5,800 7.235 69 6,000 0.010 70 6,200 7.226 0.019 71 6,400 7.217 0.028 72 6,600 7.207 0.038 73 6,800 7.198 0.047 74 7.170 0.075 7,000 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

HS-2 Pumping Test
Test Site: Enviro-Chem
Location: Zionsville, Indiana
Depth-to-water: 8.410'

Well HS-1A Readings
Test Conducted on: 11-09-98
Test Conducted by: TK & TJW

Reading	Pump test duration	Water level	Change in Water Level	Comments:
	[min.]	(ft)	[ft]	
1	0	8.410	0.000	
2	240	8.300	0.110	
3	360	8.330	0.080	
4	720	8.140	0.270	
5	1080	8.040	0.370	*******
6	1200	8.110	0.300	
7	2400	8.600	-0.190	
8	2520	8.620	-0.210	· · · · · · · · · · · · · · · · · · ·
9	2640	8.640	-0.230	
10	2760	8.640	-0.230	
11	2880	8.640	-0.230	
12	3120	8.640	-0.230	
13	3360	8.640	-0.230	
14	3600	8.640	-0.230	
15	3840	8.640	-0.230	
16	4080	8.700	-0.290	
17		8.700	-0.290	
	4320	8.730		
18	4560		-0.320	
19	4800	8.730	-0.320	
20	5040	8.730	-0.320	
21	5280	8.730	-0.320	<u></u>
22	5520	8.730	-0.320	
23	6000	8.730	-0.320	
24	6360	8.730	-0.320	
25	6720	8.730	-0.320	
26	7000	8.730	-0.320	
27				
28				······································
29				
30				
31				
32		··-		
33				
34		······································		
35		· · · · · · · · · · · · · · · · · · ·		
36	<u> </u>	· · · · · · · · · · · · · · · · · · ·		
37				
38				
39	ļ <u></u>			
40				
41				
42				
43	<u> </u>			
44				
45				
46				
47				
48				
49				
50				

HS-2 Pumping Test Well S-2 Readings Test Site: Enviro-Chem Test Conducted on: 11-09-98 Location: Zionsville, Indiana Test Conducted by: TK & TJW Depth-to-water: 9.740 Pump test duration Water level Change in Water Level Reading Comments: [min.] [ft] [ft] 1 0 9.740 0.000 2 1200 9.420 0.320 3 1920 9.540 0.200 4 2280 9.720 0.020 2400 9.800 -0.060 5 6 2520 9.710 0.030 7 2640 9.710 0.030 8 2760 9.720 0.020 2880 9 9.720 0.020 10 3120 9.720 0.020 11 3360 9.720 0.020 12 3600 9.720 0.020 3840 13 9.720 0.020 14 4080 0.010 9.730 4320 15 9.730 0.010 16 4560 9.730 0.010 17 4800 9.730 0.010 9.730 18 5040 0.010 19 5280 9.730 0.010 20 5520 9.730 0.010 21 6000 9.730 0.010 22 6360 9.730 0.010 23 6720 9.730 0.010 24 7000 9.730 0.010 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

HS-2 Pumping	Test		Well S-3 Readings		
Test Site: Enviro		Test Conducted on: 11-09-98			
Location: Zionsv			Test Conducted by: TK & TJW		
Depth-to-water:	•		1 1000 Ochladolod by. The a Tove		
Reading	Pump test duration	Water level	Change in Water Level	Comments:	
riodding	[min.]	[ft]	[ft]	Commonto.	
	[11111.]	[14]	""		
1	0	4.400	0.000		
2	60	4.340	0.060		
3	360	4.310	0.090		
4	390	4.240	0.160		
5	420	4.140	0.260	·	
6	450	4.140	0.260		
7	480	4.140	0.260		
8	540	4.140	0.260		
9	600	4.140	0.260		
10	660	4.140	0.260		
11	720	4.140	0.260		
12	840	4.140	0.260		
13	960	4.140	0.260		
14	1080	4.140	0.260		
15	1200	4.140	0.260		
16	1320	4.140	0.260		
17	1440	4.140	0.260		
18	1560	4.140	0.260		
19	1680	4.140	0.260	·	
20	1800	4.140	0.260		
21	1920	4.200	0.200		
22	2400	4.320	0.080		
23	2520	4.320	0.080		
24	2640	4.320	0.080		
25	2760	4.320	0.080		
26	2880	4.320	0.080		
27	3120	4.320	0.080		
28	3360	4.320	0.080		
29	3600	4.320	0.080		
30	3840	4.420	-0.020		
31	4080	4.420	-0.020		
32	4320	4.420	-0.020		
33	4560	4.420	-0.020		
34	4800	4.420	-0.020		
35	5040	4.420	-0.020		
36	5280	4.420	-0.020		
37	5520	4.420	-0.020		
38	6000	4.420	-0.020		
39	6360	4.420	-0.020		
40	6720	4.420	-0.020		
41	7000	4.420	-0.020		
42					
43					
44				· · · · · · · · · · · · · · · · · · ·	
45	1				
46	<u> </u>				
47		** ** **			
48	1				
49	 				
50	 		 		
	, 				


. .


HS-2 Pumping Test Well T-9 Readings Test Site: Enviro-Chem Test Conducted on: 11-09-98 Location: Zionsville, Indiana Test Conducted by: TK & TJW Depth-to-water: 2.900' Pump test duration Change in Water Level Reading Water level Comments: [min.] [ft] [ft] 2.900 0.000 0 1 15 2.720 0.180 2 75 2.830 0.070 3 420 2.710 0.190 4 5 450 2.630 0.270 1080 2.300 0.600 6 2.320 0.580 7 1320 8 1920 2.700 0.200 2280 0.170 2.730 9 10 2400 2.810 0.090 2520 2.840 11 0.060 12 2640 2.910 -0.010 13 2760 2.900 0.000 14 4080 2.920 -0.020 15 4320 2.930 -0.030 2.930 -0.030 16 4560 17 4800 2.930 -0.030 18 5040 2.930 -0.030 5280 2.930 -0.030 19 2.930 20 5520 -0.030 6000 2.930 -0.030 21 6360 2.930 -0.030 22 23 6720 2.930 -0.030 7000 2.930 -0.030 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50


HS-2 Pumping Test Well IW-5 Readings Test Site: Enviro-Chem Test Conducted on: 11-09-98 Location: Zionsville, Indiana Test Conducted by: TK & TJW Depth-to-water: 4.510 Change in Water Level Pump test duration Water level Reading Comments: [min.] [ft] [ft] 1 0 4.510 0.000 2 210 4.230 0.280 3 225 4.230 0.280 4 240 4.230 0.280 5 270 4.230 0.280 6 300 4.230 0.280 7 330 4.230 0.280 8 360 4.100 0.410 9 1080 4.000 0.510 10 1920 4.230 0.280 11 2400 4.440 0.070 12 2520 4.510 0.000 13 2640 4.510 0.000 14 2760 4.510 0.000 15 2880 4.510 0.000 3120 4.510 0.000 16 17 3360 4.510 0.000 18 3600 4.510 0.000 3840 4.600 -0.090 19 20 4080 4.620 -0.110 21 5040 4.620 -0.110 22 5280 4.620 -0.110 23 5520 4.620 -0.110 24 6000 4.620 -0.110 25 6360 4.620 -0.110 26 6720 4.620 -0.110 27 7000 4.620 -0.110 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50





ATTACHMENT C Drawdown Versus Time Plots

























ATTACHMENT D Hydraulic Conductivity Calculations

DATA SET: HS-2

CLIENT: Enviro-Chem Site DATE: 09-NOV-98 LOCATION: Zionsville, Indiana WELL NO.: HS-2 COUNTY: Clinton WELL DEPTH: 18.00 ft PROJECT: Well Pump Test Data WATER TABLE: 12.410 ft AQUIFER: Endless THICKNESS: 5.59 ft CASING RADIUS: 0.167 ft INTAKE RADIUS: 0.416 ft SCREEN TOP: 6.000 ft SCREEN BASE: 16.00 ft INITIAL HEAD: 1.159 ft TRANS. RATIO: 1.0000

MODEL PARAMETERS:

TRANSMISSIVITY: 6.55E-5 square ft/sec


CONDUCTIVITY: 1.17E-5 ft/sec

MODEL TYPE: UNCONFINED PARTIALLY PENETRATED AQUIFER (Bouwer & Rice)

No.	TIME	Head, H	(ft)	DIFFERENCE
	(secs)	DATA	SYNTHETIC	(percent)
1	30.00	1.15	1.27	-10.13
2	35.00	1.05	1.24	-17.73
3	40.00	1.06	1.20	-13.58
4	45.00	1.08	1.17	-8.58
5	50.00	1.08	1.14	-5.65
6	55.00	1.08	1.11	-2.80
7	60.00	1.01	1.08	-6.52
8	120.0	0.617	0.780	-26.48
9	180.0	0.437	0.562	-28.64
10	240.0	0.361	0.404	-12.17
11	300.0	0.294	0.291	0.780
12	360.0	0.237	0.210	11.33
13	420.0	0.190	0.151	20.33
14	480.0	0.161	0.109	32.27
15	540.0	0.133	0.0785	40.94
16	600.0	0.114	0.0565	50.37
17	1200.0	0.00100	0.00213	-112.8

CURRENT RESOLUTION MATRIIX NOT AVAILABLE

^{*} SMC Environmental Services Group



Z-SH



ATTACHMENT E Laboratory Analytical Results



Indianapolis Division 6964 Hillsdale Ct. Indianapolie, IN 46250 Tet: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Greg Scarpone HANDEX OF INDIANA 8579 Zionsville Rd. Indianapolis, IN 46268

11/19/1998

NET Job Number: 98.07787

Page 1 of 2

Enclosed are the Analytical Results for the following samples submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: ENVIROCHEM

Sample Date Date Number Sample Description Taken Received 224038 FT 11/10/1998 11/10/1998

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples analyzed.

Reproduction of this analytical report is permitted only in its entirety.

Project Representative

Lan Barnes



Indianapolis Division 6964 Hilisdale Ct. Indianapolis, IN 46250

Tel: (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Greg Scarpone HANDEX OF INDIANA 8579 Zionaville Rd. Indianapolis, IN 46268 11/19/1998

Sample No.: 224038 Job No.: 98.07787 P.O. NO.:

Page 2 of 2

Sample Description: PT Job Description: ENVIROCHEM

Date Taken: 11/10/1998

Date Received: 11/10/1998

Parameter	Result	Flag	Units	Analyst/ Date of Analysis	Method Number	Reporting <u>Limit</u>
2 42 4 m 0 0 5 L	140H 45 H	عالمية				
VOLATILES-8260 (AQ)						
1,1-Dichloroethane	33		ug/L	out / 11/16/1998	SW 8260B	<5.0
cis-1,2-Dichloroethene	4000		ug/L	out / 11/16/1998	SM 8260B	<5.0
trans-1,2-Dichloroethene	130		ug/L	out / 11/16/1998	SM 8260B	<\$.0
Sthylbenzens	120		ug/L	out / 11/16/1998	SW 8260B	45.0
Methylene chloride	<10.		ug/L	out / 11/16/1998	EW 9260B	<10.
Tetrachloroethene	6.0		ug/L	out / 11/16/1998	SW 8260B	<5.0
Toluene	1600		vg/L	out / 11/16/1998	SW 82609	<\$.0
1,1,1-Trichloroethene	310		ug/L	out / 11/16/1998	SW 82603	<\$.0
1,1,2-Trichloroethane	<\$.0		ug/L	out / 11/16/1998	SW 8260B	<5.0
Trichloroethene	<5.0		ug/L	out / 11/16/1998	SW 8260B	<5.0
Vinyl chloride	780		ug/L	out / 11/16/1998	SW 8260B	<2.0
SURR: Toluene-d8	92		89-1100	out / 11/16/1998	SW 8260B	
SURR: Dibromofluoromethace	83		86-1184	out / 11/16/1998	SW 8260B	
SURR: 4-Bromofluorobenzene	119		86-115#	out / 11/16/1998	SW 9260B	



Indianapolis Division 6964 Hillsdale Ct. Indianapolis, IN 46250 Tet (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Greg Scarpone HANDEX OF INDIANA 8579 Zionsville Rd. Indianapolis, IN 46268

12/02/1998

NET Job Number: 98.07859

Page 1 of 2

Enclosed are the Analytical Results for the following samples submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: ENVIROCHEM

Sample Number Sample Description

Date Taken

Date Received

224270 FT2

11/13/1998

11/13/1998

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples

Reproduction of this analytical report is permitted only in its

La Buneis Project Representative



Indianapolis Division 6964 Hillsdale Ct, Indianapolis, IN 46250

Tet (317) 842-4261 Fax: (317) 842-4286

ANALYTICAL REPORT

Mr. Greg Scarpone HANDEX OF INDIANA 8579 Zionsville Rd. Indianapolis, IN 46268 12/02/1998

Sample No.: 224270 Job No.: 98.07859

P.O. NO.:

Page 2 of 2

Sample Description: FT2 Job Description; ENVIROCHEM

Date Taken: 11/13/1998

Date Received: 11/13/1998

<u>Parameter</u>	Result	Plaq	<u>Unit</u>	Analyst/ Date of Analysis	Method Number	Reporting Dimit
VULATILES-8260 (AQ)						
1,1-Dichloroethene	54.		ug/L	tjg / 11/25/1998	SW 8260B	<5.0
cis-1,2-Dichloroethene	4,300	e	ug/L	tjg / 11/25/1958	SW 9260B	<5.0
trans-1,2-Dichloroethene	180.		ug/L	tjg / 11/25/1999	5W 9260B	<5.0
Ethylbenzene	110.		ug/Ļ	tjg / 11/25/1998	SW 8260B	<5.0
Methylene chloride	110.		ug/L	tjg / 11/25/1998	SW 826CB	<10.
Tetrachloroethene	8.9		ug/L	tjg / 11/35/1998	SM 8260B	<5.0
Tolueno	<5.0		ug/L	tig / 11/25/1998	SW \$260B	∢5 .0
1,1,1-Trichloroethane	1,000.	e	ug/L	tjg / 11/25/1998	SW 92603	<5.9
1,1,2-Trichloroethane	<5.0		ug/L	tjg / 11/25/1998	SM 8260B	<5.0
Trichloroethene	<5.3		ug/L	=jg / 11/25/1998	SW 8260B	<5.0
Vinyl chloride	1,700.	•	ug/L	tjg / 11/25/1998	SW 8260B	<2 .0
SURR: Toluens-d8	102.		88-1104	cjg / 11/25/1998	SW 8260B	
SURR: Dibromofluoromethane	121.		86-1184	tjg / 11/25/1999	SW 9260B	
SURR: 4-Bromofluorobenzene	101.		86-115%	tig / 11/25/1998	SW 8250B	